The Pavilion hinge is the most common HP failure in Nairobi. The hinge stiffens, the plastic mounts crack, and the screen bezel separates from the lid. Caught early it is a hinge repair; ignored it Browse this site becomes a display replacement. Hinge notes at %LINK%.